Created On: Tuesday, 09/21/2021

## **Interruption Details**



## **Detail For Interruption INT-14969:**

AOR: NORTH STATE Start DTS: 07/14/2021 10:58:00 TABLE MTN Jurisdiction: Aware DTS: 07/14/2021 10:58:00

Line End DTS: ResourceType:

Caribou-Table Mountain Resource: Wiredown: Forced: 

230 kV Interruption CAP Number: Voltage:

Line Or Apparatus:

## System Protection Details:

**Protection Review:** 

Double - Ended Yes **Correct Operation: Location Method:** 

MisOperation: No Cause: Fire Complete Phase Involved in Fault: AB **Protection Review Status:** 

**SubStation Location 1:** SubStation Location 3: Loc1 Target Data Provided by: Loc 3 Target Data:

Loc1 Target Data: Loc 3 Target Data Provided By: Loc 3 Able to Dial Into Relay Loc1 Able to Dial Into Relay

Resource: Remotely:

SubStation Location 2: Updated By: 19-Jul-2021 11:35:39 Loc2 Target Data Provided by: **Updated DTS:** 

Line

Loc2 Target Data: Outage Type:

Loc2 Able to Dial IntoRelay **NERC Reportable:** Resource: Responsible Engineer:

**Protection Jurisdiction:** North +/- 1 mile Accuracy of Location:

\\utility.pge.com\projects\I Record Location:

**Fault Location Provided:** 

X.Y miles from CCC terminal/bus/switch/junction **Actual Location:** 

34 miles from Table Mountain Fault Location1:

Fault Location1 Details: Structure 027/197

X.Y miles from CCC terminal/bus/switch/junction Fault Location2:

Fault Location2 Details: Structure xx/yy

**Additional Details:** Dixie Fire in the area.

MisOperation Event Analysis:

MisOperation Categary: RSA Operated:

**Primary Casue MisOperation:** 

System Protection Components that MisOperated:

Relay Technology: CAP ID:

MisOperation details:

**Additional Comments:** 

Page 1 of 2 Confidential

Detail For Interruption INT-14969:	
RAS Tab:	
Name of RAS Scheme(s) Involved:	
PRC-012/R5.1.1 The System events and/or conditions appropriately triggered the RAS: Details:	
PRC-012/R5.1.2 RAS responded as designed: Details:	Responsible Protection Engineer:
PRC-012/R5.1.3 RAS was effective in mitigating BES performance issues it was designed to address:  Details:	
Responsible Operations/RAS Engineer:	
PRC-012/R5.1.4 RAS operation resulted in any unintended or adverse BES response:  Details:	
Responsible Operations/Transmission Planning Engineer:	
PRC-012/R5.2 Results of RAS operational performance analysis	
Date Provided: Responsible RAS Engineer:	
RAS / OE Record Location:	
RAS Cap Number: 0 RAS Cap Details:	
Reference Cards: Ref	erence Interruptions:
Reference Logs: Epage Sent: 07/14/2021 10:58 Caribou-Table Mountain, 230 kV, Line, Op	pened-Relayed-Did Not Test
At 07/14/2021 11:04 TSM&C/EPAGE NTFD at 07/14/2021 10:58 Caribou Not Test	-Table Mountain, 230 kV, Line, Opened-Relayed-Did
At 07/14/2021 11:02 DO/ NTFD at 07/14/2021 10:58 Caribou-Table Mountain, 230 kV, Line, Opened-Relayed-Did Not Test	
At 07/14/2021 10:59 SDV/I NTFD at 07/14/2021 10:58 Caribou-Table Mountain, 230 kV, Line, Opened-Relayed-Did Not Test	
07/14/2021 10:58 Became aware of INT-14969 for Caribou-Table Mountain, 230 kV, Line, Opened-Relayed-Did Not Test	
07/14/2021 10:58 Started INT-14969 for Caribou-Table Mountain, 230 kV, Line, Opened-Relayed-Did Not Test	
Page 2	of 2 Confidential