
From:
To: PG O&M Rock Crk Ops
CC: [REDACTED]
Sent: 7/14/2021 8:51:46 AM
Subject: FW: Rock Creek Dam
Attachments: IMG_2203.jpg

Ops,

Attached is a picture of what appears to be a jumper that has been cut at Cresta Dam. This jumper looks like it is supposed to drop down into the transformer. I stopped by Rock Creek Dam and did not see an broken jumpers, Can you confirm this is a cut jumper and not the lightning arrestor?

Thanks,
[REDACTED]

From: [REDACTED]
Sent: Tuesday, July 13, 2021 3:18 PM
To: [REDACTED]
Subject: FW: Rock Creek Dam

I think this is Cresta Dam? [REDACTED] Thought it was Rock Creek Dam

[REDACTED]

Power Generation Supervisor
DeSabra Hydro – Electrical and Mechanical

[REDACTED]



From: [REDACTED]
Sent: Monday, July 12, 2021 5:42 PM
To: [REDACTED]
Subject: Rock Creek Dam

[REDACTED]

I was out trying to help Project Management scope the remaining UG , was trying to get the bank size and voltage and saw a jumper cut. Is there anyone that can validate loads for the facility? Since it's not metered there is no data.

Let me know if the jumper needs to be fixed and I can check with M& C

Thanks
[REDACTED]

Supervisor- Construction Management
Distribution Electric