

# SHIFT TURNOVER CHECKLIST

DATE: 7-12-21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: \_\_\_\_\_  
OPERATOR SIGNATURE: \_\_\_\_\_

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: THURST BRG HIGH TEMP #1; MCN 5 Flow IN/OUT  
NF BR IN/OUT 1 TIME BK 2 NITROGEN

DATE: 7-13-21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: \_\_\_\_\_  
OPERATOR SIGNATURE: \_\_\_\_\_

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: max line voltage til 2000 FFE above crest dam,  
#1 Thrust BR begining temp high; cresta dam standby gen running

Internal



# SHIFT TURNOVER CHECKLIST

DATE: 7/13/21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE:   
OPERATOR SIGNATURE: \_\_\_\_\_

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: FIRE, NF 23, #1 THRUST BKG HI TEMP, #1 IN LOCAL AUTO PER   
ROCKS 1101 SW 941: CRESTA DAM STOPY  STARTING THERE?  
EAP TESTING TODAY AT 12 BUCKS. STARTING BUCK #1 FOR SPIN RES  
CRESTA RIO OSO STILL OUT (280 WAD RESTRICTION)

DATE: 7-14-21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE:   
OPERATOR SIGNATURE: \_\_\_\_\_

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: Fire in canyon  
Oil samples on U1 + U2 RCP  
UGB high temp alarm cleared  
Bucks U1 para + high B2B temp  
Standby gen @ Cresta alarm  
NE70 ramping  
Both Pae units Reserve S/D

Internal

Rock Creek Operations, Rock Creek Switching Center  
EAP TESTING Bucks area  
Bucks U1U #4 open

SHIFT TURNOVER CHECKLIST

DATE: 7/14/21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: \_\_\_\_\_  
OPERATOR SIGNATURE: \_\_\_\_\_



- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: 10 MW Bucks 1 CARD UNTIL 10:00 | Bucks 1101 DE-ENERGIZED  
NF70 640 CFS

DATE: 7-15-21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE \_\_\_\_\_  
OPERATOR SIGNATURE \_\_\_\_\_



- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA



NOTES: Viesel Gen Crestler / Clearances  
Bucks w/ BZB temp alarms  
Resubla load lowered  
Doc UZ Para

Internal



# SHIFT TURNOVER CHECKLIST

DATE: 7-15-21  
SHIFT: DAY / NIGHT


OPERATOR SIGNATURE:   
OPERATOR SIGNATURE: 

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: Poe2 para, Books Alarm/trip points adjusted  
Cresta Dam on Bieselgen.  
May be Evacuated to Caribou

DATE: 7/16/21  
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE:   
OPERATOR SIGNATURE: 

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: NORMAL VOLTAGE; SIP T; CRESTA DAM;