# Thank you!

HR Emergency Management Specialist, Principal

From: Sent: Wednesday, July 14, 2021 11:36 AM To:

Subject: RE: Report #1 (Initial) - Dixie, Oroville, Butte County

Same order # is used for all employee support (lodging and financial assistance in the event of a lost/uninhabitable home)

From: Sent: Wednesday, July 14, 2021 11:07 AM

То:

Subject: FW: Report #1 (Initial) - Dixie, Oroville, Butte County

Team,

We are tracking an additional fire which includes evacuations. The HAWC provided its update in the link below. HR is waiting for the zip code analysis in order to conduct its impacted personnel report. HR will engage the North Valley OEC leadership when its activated.

will the same finance order code used for the River Fire be used for employee impacts for the Dixie Fire? Please let me know.

#### https://pge.sharepoint.com/sites/EOCResources/EOC%20INCIDENTS/FORMS

ALLITEMS.ASPX?RootFolder=%2Fsites%2FEOCResources%2FEOC%20Incidents%2F2020%20EOC%20Incidents%2F2020%2E08%2E16%20Capacity%20Emergency%20Event%2FPlanning%2FReports%2FEvacuation%20Orders%2F2021%5FEvacuation%20Reports& FolderCTID=0x012000E7E71D6513813C4AA1FA960201F14F8D&View=%7B3645E8A3-A8D2-46E4-8FAB-D519557B4C43%7D

HR Emergency Management Specialist, Principal

From: Sent: Wednesday, July 14, 2021 10:18 AM To: Subject: Report #1 (Initial) - Dixie, Oroville, Butte County



Incident Report Number: 1 (Initial) Date: 07/14/21 Time: 1017 Incident Type: Vegetation Incident Name: Dixie Lead Agency: USDA Forest Service/CAPNF - Plumas National Forest / CAL FIRE

Incident Location: HWY 70 <u>39,874,-121,378</u> City/Community: Oroville County: Butte PG&E Division: North Valley

#### PSS Assigned:

FIA: 248 Tier: Tier 3 Acreage: 1,200 Containment %: 0 Outages: Yes Max Customers Impacted: 4 Current Customers Impacted: 3

### Current Summary:


The Dixie Fire is approximately 1,200 acres, 0% contained and burning in steep and inaccessible terrain north of Highway 70 and west of Merlin, underneath PG&E's Distribution and Transmission line assets. The fire has come out of the Feather River Canyon bottom and has reached the ridgetop near the Caribou-Table MTN – 230kV lines. The fire is currently burning upslope, upcanyon to the east, northeast and under normal diurnal summertime burning conditions. CAL FIRE is attempting to get ground resources to the ridgetop along the 300 U Line road in an attempt to stop the forward rate of spread using dozers and fixed wing aircraft. This fire is very dynamic and lag time for getting ground resources in place will be the challenge for firefighters.


Last night at 2030 hours, CAL FIRE requested PG&E to deenergize the Bucks Creek 1101 circuit from SSD 941, affecting three customers for firefighter safety. T-line Supervisor and the s

## Smoke visible on multiple wildfire cameras.

Assets Potentially at Ris	<u>sk:</u>
<ul> <li>Distribution:</li> </ul>	Bucks Creek 1101
• Transmission:	Bucks Creek-Rock Creek-Cresta – 230kV, Caribou-Palermo – 115kV, Rock Creek-Poe – 230kV, Caribou-Table Mtn – 230kV
• Gas T and D Line:	None at this Time
• Telecom:	None at this Time
• Hydro:	Cresta Dam
Others:	None at this Time

Overview:





Orientation:



```
Hazard Awareness & Warning Center (HAWC)
To Subscribe to HAWC Incident Reports, please submit request to
```

Some of the measures included in this document, email, presentation, or study are contemplated as additional precautionary measures intended to further reduce the risk of wildfires.