

---

**From:** [REDACTED]  
**To:** [REDACTED]  
**Sent:** 7/14/2021 11:47:54 AM  
**Subject:** RE: Caribou-Table Mountain 230kV line (sustained)

Thanks. I'm on the Trans-Sub distribution list.

---

**From:** [REDACTED]  
**Sent:** Wednesday, July 14, 2021 11:32 AM  
**To:** [REDACTED]  
**Subject:** FW: Caribou-Table Mountain 230kV line (sustained)

Classification: [Internal](#)  
FYI....

---

**From:** [REDACTED]  
**Sent:** Wednesday, July 14, 2021 11:29 AM  
**To:** [REDACTED]  
**Subject:** Caribou-Table Mountain 230kV line (sustained)

Preliminary Report:

1058 Caribou-Table Mountain 230kV line relayed and did not test due to automatic reclosing disabled due to Dixie Fire. On the trouble, Caribou PH #1 and #2 and SPI Quincy separated. Caribou 230kV 115kV and 60kV busses, #9-230/13.8kV transformer, #11-230/115/60kV transformer bank and #2-115/12kV transformer de-energized. Caribou #2, Caribou-Plumas JCT, Hamilton Branch-Chester 60kV lines de-energized. Sustained interruption to Chester (1659), Collins Pine (1), Hamilton Branch (2382), Grays Flat (125), East Quincy (1572), Gansner (1730), SPI Quincy, Plumas Sierra (1), Spanish Creek (922) and Big Meadows (2620). Caused by Dixie fire.

Switching in progress to create Caribou Island and restore customers.

[REDACTED]  
*Senior Transmission System Dispatcher  
Vacaville Grid Control Center*

