From: To: CC: Sent:	1/11/2021 9:50:21 AM
Subject:	RE: Scoping Documents for Keswick & Bucks Creek

1 is mainline the other is a tap line

## Thank You,

From: Sent: Monday, January 11, 2021 8:38 AM To: Cc: Subject: RE: Scoping Documents for	Keswick & Bucks Cree	ak

Everything is in the Post Field Check section now. On a side note, you overstated the miles on the Iron Mtn Rd section by 1.43 miles. See below.

Mitch

Trench / Bore	3.04 miles – Iron Mountain Road
Trench / Bore	1.63 Miles – Iron Mountain Road

From: Sent: Monday, January 11, 2021 7:47 AM			
To: Cc:			
Subject: RE: Scoping Documents for	Keswick &	Bucks Creek	

I need to ask that you please put all the notes from your review after the Post Field Check Results section. By adding notes to the Field desktop you are changing what we reviewed and proposed. Can I ask that you have these corrected today?

For example, the desktop review proposed a DER under the section Overhead Line Elimination will need to be confirmed or rejected under the same section after the Post Field Check Results. Please call me with any questions or concerns.

Thank You,

From: Sent: Monday, January 11, 2021 7:40 AM To: Cc: Subject: RE: Scoping Documents for	Keswick &	Bucks Creek	

Notes are in yellow highlight. If you have questions, please let me know and I will clarify where needed.

From:		
Sent: Sunday, January 10, 2021 9:32 AM		
To:		
Cc:		
Subject: RE: Scoping Documents for	Keswick &	Bucks Creek

I am just checking in to see the status of returning these documents completed with your review? Will you have them early this week so we can continue with the scoping approval process?

Thank You,

From:	
Sent: Tuesday, January 5, 2021 3:43 PM	
То:	
Cc:	
Subject: Scoping Documents for K	eswick & Bucks Creek

Please review, segment and return the completed Field Scoping Documents to me as soon as you can so we can continue with the scoping approval through the Wildfire Governance Committee. Please let me know if you have any questions or concerns.

Thank You,



PGE-DIXIE-NDCAL-00000804

PGE-DIXIE-NDCAL-00000805