PM: 35217272	Project Name: SH - KESWICK 1101 LR 1586		
Notification: 120048018	Region: Northern	City: Redding	
Project Manager:	Division: North Valley	County: Shasta	

## Proposed Project Scope1:

				Desktop Meeting Results			ADE Fielding Results		
		Miles	Unit Cost (\$M)	Total Cost (\$M)	Miles	Unit Cost (\$M)	Total Cost (\$M)		
Harden in Place (OH only)				\$ 7.23			\$ 4.91		
Convert OH to UG	Convert OH to UG			\$ 31.26			\$ 21.00		
Relocation (OH to	Relocation (OH to OH location)			\$ 0.00			\$ 0.00		
Remove Reconfigure				\$ 0.00			\$ 0.00		
	Add			\$ 0.00			\$ 0.00		
Totals				\$ 38.49			\$ 25.91		

<sup>1.</sup> This table is to be filled out by Project Manager detailing the change in units and costs before and after the Field Scoping Process is completed.

A) Field Scoping Team - Desktop Meeting Notes

The following are required outputs to be discussed in the meeting:

- · Main Route(s) of Egress
- Land and Environmental Risk(s)
- Vegetation density and risk assessment
- Construction review (area(s) of concern)

Additional Option(s) or Comment(s):

### **BIO CONSTRAINTS**

- 1. There is California red-legged frog and Foothill yellow-legged frog MRHCP modeled habitat within the project area, no constraints as long as species-specific AMMs are implemented.
- Could require work during the dry season (May 15 Oct 15) and/or biomonitoring.
- There are multiple water crossings. Potential Permitting\*

#### **CULTURAL CONSTRAINTS**

Entire Project:

Numerous cultural resources within the project area.

Cost: Fieldwork will include monitoring on portions of OH and all UG. Site record updates (esp. BLM land) and survey of access routes. Field work is anticipated to take at least 5-6 weeks.

#### **EFS CONSTRAINTS**

#### No Constraints

#### **PSS REVIEW**

## Location, Fuel Types and Population Density:

- The Keswick 1101 project is in Shasta County. Project originates near the community of Keswick and continues north along Iron Mountain road
- Fuel types are consistent with grass, brush, and intermixed patches of conifers. Fuel loading can be very light to heavy in places; however, fuels have been significantly reduced in the project area due to the 2018 Carr Fire.
- The community of Keswick is at the southern end of the project and the population would be considered low. After the project heads north from Keswick, the area is sparsely populated. South of the project is the small mountain community of Shasta.
- To the east and south of the project is the City of Redding.

## Fire History:


- This area has significant fire history directly impacting the project area. The Carr Fire 2018, Bully Fire 2014, Clover Fire 2013, SHU Lightning 2008.
- All of these fires were not directly in the project footprint area but show the ability of the area fuels to resist containment and have a fire become a major fire.

## Routes of travel for first responders and evacuees if a fire happens:


- Most of the project is along Iron Mountain road, which is the only route of travel for evacuating the few residents living north of the community of Keswick to Highway 299W.
- If the evacuation route to the south was cut off in the community of Keswick, the residents would have to either shelter in place or use a series of dirt roads, often blocked by locked gates, to travel north to the Shasta OHV park/Shasta Dam day use area.
- First responders would use Rock Creek and Iron Mountain roads from the south to make access to the area.
- This portion of the Keswick 1101 serves the 4,400-acre Iron Mountain Mine site and its operation of a full-scale neutralization system, responsible for the collection of contaminated water runoff for treatment, significantly reducing acid and metal contamination in surface water at the site.
- Iron Mountain road is the access point for PG&E crews to service and maintain ED assets supplying South Fork Lookout Peak telecom sites for power.

# Attachments/Images:

A) **Project Area** – Google Earth Image with Circuit and HFTD Tier 2 Tier 3 Overlay



B) Fire History – WIFire Map at <a href="https://firemap.sdsc.edu/">https://firemap.sdsc.edu/</a> to produce the fire history image.



Note:	Note:							
Originally pro	Originally proposed to Not an option per							
103934127 to	101456258 1.9 ı	miles – 4 Tx. Appears the	e load is too great for Remote Grid.					
		Desk-Top	Review Results					
•	necklist is to be une maximum ext	•	alyze the project to determine final scope to eliminate/mitigate					
Overhead Lir	ne Eliminatio	n:						
Yes □ No ✓ <b>DE</b>	R alternatives to	consider (these locatio	on(s) to be sent to					
Yes □ No ✓ <b>Idl</b>	es □ No ✓ Idle facilities to remove (These location(s) to be sent to							
Yes □ No ✓ <b>Re</b>	res □ No redundant ties to remove (These location(s) should be run through Distribution Reliability Planning)							
SAP Equip. ID	SAP Equip. ID	OH Elimination Type	Additional Notes:					
(Start)	(Finish)	(DER, Idle, Tie Rem.)						
1******	1*******							
1******	1*******							
1*******	1******							
1*******	1*******							
1*****	1*****							

# Overhead to Underground Conversion:

Yes  $\checkmark$  No  $\square$  Lines to be considered for UG (These location(s) to be sent to

SAP Equip. ID	SAP Equip. ID	Trench, Bore, or	Additional Notes:
(Start)	(Finish)	Plow-in	
103922836	103934187	Trench / Bore	0.20 miles - Include branch to SAP ID 101466013.
101463252	1******	Trench / Bore	0.17 miles - Ends east towards down personal drive. Tie in to proposed UG on Iron Mountain Road
101469508	101463219	Trench / Bore	2.38 miles – Iron Mountain Road
101469423	101463365	Trench / Bore	0.20 Miles – Iron Mountain Road
101463369	101463365	Trench / Bore	0.12 miles – east of Iron Mountain Road
1******	1******		
1******	1******		
1******	1******		
1******	1******		
1******	1******		
1******	1******		
1******	1******		
1******	1******		

There are several factors that should be considered in identifying these potential overhead to underground

conversions:			
Is there a viable	route available?	Is there a dedicated street/	easement available?
What is the feas	sibility of new la	nd rights?	
What is the soil	condition?		
Are there a sign	ificant number o	f service drops, tap-lines, or otl	ner overhead equipment?
Relocation o	f Facilities		
Relocation o	racincies.		
Yes □ No ✓ Lin	es to be conside	ered for relocation (These locat	ion(s) to be sent to
SAP Equip. ID	SAP Equip. ID	OH, Trench, Bore, or Plow-in	Additional Notes:
(Start)	(Finish)	56 # N	
1******	1******		
1******	1*******		
1*******	1******		
1******	1******		
1******	1*****		
1******	1******		
	<b>.</b>	<u> </u>	
			prepared for in scoping a CWSP project. The following
examples should	d be considered,	and teams should be invited to	participate:
Rapid Ea	arth Fault Curren	nt-Limiter (REFCL) — This system	can detect phase-to-earth faults. They then cancel the
			and limit the voltage of the fault to below the point where
it can st	art a fire. This is	only applicable on 3 wire syste	ms and it requires significant modifications to the
circuits.			
0	Yes □ No ✓ <b>Cir</b>	cuit being considered for REFC	L? (Please include
0	If Yes, then Syste	em Automation will need to pro	ovide Planning support in adjusting necessary scope to
	support a future	REFCL protection scheme.	
Resilien	cv 70nes (R7)- Th	nese are areas deemed critical i	n nature to support life and health in an area during
			, underground is required. This needs to be considered
-	esigning these zo		,
		cuit being considered for an R	Z? (Please include

o If Yes, additional UG and SCADA equipment may be required to support. Microgrid Strategy

RZ's in the area.

Implementation will need to provide Planning support in adjusting necessary scope to allow for future



### Post Field Check Results

The following section will allow for brief notes from the field inspection and/or engineering analysis conducted to determine final scope recommendations.

#### Overhead Line Elimination:

Copy each location from the Desk-top review notes from the Overhead line Elimination recommendations and provide an affirmative response to each proposed location. The notes should be clear as to the post-field check recommended actions so that Distribution Planning can update the scoping documents.

SAP Equip.	SAP Equip.	OH Elimination Type	OK to	Field or Engineering Notes*
ID (Start)	ID (Finish)	(DER, Idle, Tie Rem.)	Proceed	
7,500	2		(Y,N, N/A)	
1******	1******		N/A	
1******	1******		N/A	
1******	1******		N/A	
1******	1******		N/A	
1******	1******		N/A	

<sup>\*</sup>Please begin notes with LAN-ID of Estimator or Engineer who completed in analysis

### Overhead to Underground Conversion:

Copy each location from the Desk-top review notes from the Overhead to Underground Conversion recommendations and provide an affirmative response to each proposed location. The notes should be clear as to the post-field check recommended actions so that Distribution Planning can update the scoping documents. Also, clear note the recommended Underground construction method Trench, Bore, or Plow-in.

SAP Equip.	SAP Equip.	Trench, Bore, or	OK to	Field Notes*
ID (Start)	ID (Finish)	Plow-in	Proceed	
			(Y,N,N/A)	MGCf
103922836	103934187	TRENCH	YES	SECTION 1: (0.20 mi) MAINLINE & LOCAL W/
				SECONDARY; SMALL LOTS; LAND RIGHTS; .3 MILES
				TO INCLUDE SECONDARY POLES
101463252	1******	Trench / Bore	YES	SECTION 4: (0.17 mi) 1 PROP., 2 SVCS, NO LAND
				RIGHTS; TX NEAR 1 <sup>ST</sup> HSE
101469508	101463219	Trench / Bore	YES	SECTION 4: (2.38 mi) COMBINATION OF
				TRENCH/BORE IN ROAD 2' IN FROM FOGLINE; BOXES
				IN FREQUENT PULLOUTS; LOTS OF VEG ALONG RTE
101469423	101463365	Trench / Bore	YES	SECTION 4: (0.20 Mi) LAND RIGHTS REQ'D;
				COMBINATION TRENCH/BORE ALONG DRIVEWAY
101463369	101463365	Trench / Bore	YES	SECTION 4: (0.12 mi) TRENCH ALONG DRIVEWAY
101466962	101469508	Trench / Bore	YES	SECTION 3: RELOCATE 4325' (.82 mi) CROSS
				COUNRTY OVERHEAD LINE TO ROAD AS 4150'
				UNDERGROUND FOR RESILIENCY AND TO AVOID
				FUTURE VEGETATION MANAGEMENT AND RISK.
1*******	1******		N/A	
1*******	1******		N/A	
1*******	1******		N/A	

1******	1******		N/A	
			-	
103922244	103934073	HARDEN IN PLACE	YES	<b>SECTION 2</b> : 1550′ (0.29 mi);
101463219	103921943	HARDEN IN PLACE	YES	<b>SECTION 5</b> : 7600′ (1.44 mi)
103921944	101456258	HARDEN IN PLACE	YES	<b>SECTION 6</b> : 8121' (1.54 mi)
1******	1******		N/A	
1******	1******		N/A	
1******	1******		N/A	

<sup>\*</sup>Please begin notes with LAN-ID of Estimator or Engineer who completed in analysis

### Relocation of Facilities:

Copy each location from the Desk-top review notes from the Relocation of Facilities recommendations and provide an affirmative response to each proposed location. The notes should be clear as to the post-field check recommended actions so that Distribution Planning can update the scoping documents.

SAP Equip. ID (Start)	SAP Equip. ID (Finish)	OH, Trench, Bore, Plow-in	OK to Proceed (Y,N, N/A)	Field or Engineering Notes*
1******	1*******		N/A	
1******	1******		N/A	

<sup>\*</sup>Please begin notes with LAN-ID of Estimator or Engineer who completed in analysis

Additional Notes and attachment descriptions:



OVERALL, THE PROJECT AS SCOPED FROM DESKTOP IS GOOD. I ADUSTED SOME OF THE LENGTHS DOWN DUE TO DUPLICATION OF THE PROPOSED ROUTE WITHIN THE GIVEN SAP IDs. THE ROUTE IS VIABLE. ON IRON MTN RD. THERE WILL BE SOME LAND RIGHTS REQ'D FROM US GOV'T AND ONE NEIGHBOR, BUT MOST SHOULD FIT WITHIN ROADWAY FRANCHISE.

THE TRENCH ALONG IRON MTN RD.FOR THE MOST PART WILL BE A SINGLE LIFT WITH A LOADED DUCT AND A SPARE; BOX PLACEMENT SHOULD RANGE FROM 600' TO 800'; THERE WILL BE MINIMAL PM EQUIPMENT AND WHERE IT IS NEEDED, SHOULD BE ABLE TO PLACE IN A SAFE LOCATION.TRENCH LINE TO BE 2-3 FEET INSIDE FOGLINE. TAPLINES IN THE UG AREA N/O SPRING CREEK ARE LIMITED TO FOUR SHORT RUNS WITH FIVE SERVICES; MOST LAND IS US GOV'T, FUTURE SERVICE WORK UNLIKELY; 1 CAPACITOR BANK TO PLACE.

THERE IS ONE BRIDGE TO CROSS OVER A YEAR AROUND CREEK, WE SHOULD BE ABLE TO ATTACH TWO DUCTS TO IT. THE ROAD IS LIGHTLY TRAVELLED WITH TRAFFIC LIMITED TO LOCAL RESIDENTS/MINE AND USE OF THE GUN RANGE. TRAFFIC CONTROL COSTS SHOULD SEE REDUCTION AND POSSIBLY GREATER IF WE ARE ABLE TO CLOSE ACCESS FOR EXTENDED PERIODS.

IN KESWICK, RECL 1586 WILL NEED RELOCATION, UG TO NORTH SHOULD GO DOWN MARKET ST (ACCESSIBLE YEAR AROUND) IN EDGE OF ROAD TO BEYOND TRANS TOWER LINE AND RISER UP NEAR SAP ID 103922244. THIS SECTION WILL LIKELY REQUIRE LAND RIGHTS DUE TO SMALL LOTS, SECONDARY SYSTEM, AND TRANSFORMERS.

IN GENERAL, CLOSE PROXIMITY TO REDDING SHOULD KEEP THE SPOIL DISPOSAL COSTS DOWN (15 MINUTES ONE WAY). IF THE ROAD IS CONTROLLED BY SHASTA CO., TRENCH BACKFILL IS REQUIRED TO BE POPCORN SLURRY.

THE SOIL IN THE AREA IS LARGELY DECOMPOSED GRANITE WITH SOME OUTCROPPING OF WEATHERED ROCK; CIVIL CONSTRUCTION SHOULD BE ABLE TO OPEN TRENCH, BORE, OR A COMBINATION OF BOTH.



RECOMMEND EACH SECTION AS A SEPARATE PROJECT. IN **SECTION 2**, BARE 397A MIGHT BE CONSIDERED IN PLACE OF 397A TW DUE EXCESSIVE SAG ISSUES OR CONSIDER INSTALLING POLES FURTHER DOWN INTO GORGE TO REDUCE THE LONG SPAN IF POSSIBLE.

RECOMMEND THAT **SECTION 3** BE RELOCATED TO IRON MTN ROAD AND UNDERGROUNDED. WORK WITH **SECTION 4** AS A COMBINED SINGLE PROJECT. WHILE IT IS LONG, IT IS SIMPLE IN SCOPE WITH SIMILAR MATERIALS AT MOST LOCATIONS.

SECTIONS 5&6 HARDEN IN PLACE AND REDUCE SPANS LENGTHS WHERE POSSIBLE.

## Approval(s):

Project Manager -

Estimating -

Asset Strategy -



Date:

Date: EDRS

Date: EDRS