
From: To: 4/7/2021 2:19:51 PM Sent: Subject: FW: Site Visit Updates Attachments: April 16th SH Site Visit.docx Here's an update. The 7am time for 4/16 is not set yet. I will report back to tomorrow afternoon. They need to be back into Chico by 1pm on Friday 4/16. So I don't think we'll need to meet at 7. They also let me know that they will not have time to visit Oro Fino on Thursday. Pacific Gas and Electric Company Sent: Wednesday, April 7, 2021 9:42 AM To: Cc: Subject: RE: Site Visit Updates ******CAUTION: This email was sent from an EXTERNAL source. Think before clicking links or opening attachments.**** Attached is the updated System Hardening schedule for next week's site visit. In addition to the holes that need to be filled, should we meet earlier in the morning since there will be additional travel time? I would suggest 7 am. Thanks, Sent: Tuesday, April 6, 2021 5:50 PM To: Cct Subject: RE: Site Visit Updates

[EXTERNAL EMAIL] DO NOT CLICK links or attachments unless you have confirmed with the sender and know the content is safe.

I would suggest we meet at 400 E. Park Avenue, Chico, 95928 on Friday 4/16. We can car pool from there. It should take 45 minutes to an hour to get to the site from here.

Let me know if you disagree.

Do you know what time we want to meet up with everyone on Friday? I need to let the agencies know.



Pacific Gas and Electric Company

From:

Sent: Tuesday, April 6, 2021 3:54 PM

To:

Subject: RE: Site Visit Updates

******CAUTION: This email was sent from an EXTERNAL source. Think before clicking links or opening attachments.*****

Hi

I looked it up, and it's now called Toni's Mix'n It Up Restaurant. Address is 11975 CA-70, Oroville, CA 95965. Do you think there will be an issue if we leave a couple of rigs parked there?

Thanks,

From:

Sent: Monday, April 5, 2021 2:27 PM


To:


Subject: RE: Site Visit Updates

[EXTERNAL EMAIL] DO NOT CLICK links or attachments unless you have confirmed with the sender and know the content is safe.

Last cell service and location to meet would be across from Jarbo Gap CAL Fire Station on highway 70. The restaurant used to be called Scooters and has a large parking lot and cell service.

Once we drop below that location, we lose cell until we get down near Bucks and you have to have a booster. Each PG&E facility usually has wifi at their location also and there are three to four hydro facilities along the way depending final route.





- 35217268
- 35224712
- 35224713



Pacific Gas and Electric Company

From:

Sent: Thursday, April 1, 2021 2:59 PM

To:

Subject: FW: Site Visit Updates

******CAUTION: This email was sent from an EXTERNAL source. Think before clicking links or opening attachments.*****

Hello All!

FYI, the following is a high level snapshot of the April Site Visit agenda. No feedback yet.

I'll let you know when they've given the go ahead.

Thanks,

From:

Sent: Thursday, April 1, 2021 3:32 PM

To: Cc:

Subject: Site Visit Updates

For your consideration is the proposed site visit high level overview. Please review and let me know of any changes or recommendations.

Monday, April 12th 0800 Start Time

AM and PM – System Hardening Project with Agencies

Three projects on the Bucks Creek circuit that cover 4 miles. They are high risk score on the new risk model. They have Railroad, Caltrans, Forest Service & PG&E Hydro to manage. These projects are also 90% underground which means they won't be built until 2022. The projects are south east of Paradise.

Do you want someone from team to be included?

Tuesday, April 13th

0900 Start Time

AM - Distribution Inspect App Observation w/ Contract Inspectors

PM - Transmission Inspect App Observation

AM – (Distribution, Chico) PM – (Transmission, Oroville)

Wednesday, April 14th 0700 Start Time AM/PM – Vegetation Management

Post wildfire mitigation and EVM work in Redding, CA.

All of these projects are in the North Valley Region. Logistically, Chico looks like the best central hub for all three days.

Thanks,

