

SHIFT TURNOVER CHECKLIST

DATE: 7-12-21
 SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: _____
 OPERATOR SIGNATURE: _____

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: THRUST SRC HIGH TEMP #1; MCU 5 Flow IN/OUT
NF 02 IN/OUT ↑ TIME BK 2 NITROGEN

DATE: 7-13-21
 SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: _____
 OPERATOR SIGNATURE: _____

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: max fern voltage til 2000 FFE above cascade dam,
All Thrust SRC temp high; cascade dam standby gen running

Internal

SHIFT TURNOVER CHECKLIST

DATE: 7/13/21
SHIFT: DAY/NIGHT

OPERATOR SIGNATURE: [Redacted]
OPERATOR SIGNATURE: [Redacted]

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: FIRE, NF 23, #1 THRUST DRG HI TEMP, #1 IN LOCAL AUTO PER [Redacted]
ROCKS 1101 SW 941: CRESTA DAM STOPY [Redacted] STARTING THERE;
EAP TESTING TODAY AT 12 BUCKS; STARTING BUCK #1 FOR SPIN RES
CRESTA RIO OSO STILL OUT (280 MW RESTRICTION)

DATE: 7-14-21
SHIFT: DAY/NIGHT

OPERATOR SIGNATURE: [Redacted]
OPERATOR SIGNATURE: [Redacted]

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: Fire in canyon
Oil samples on U1 + U2 RCR
UGB high temp alarm cleared
Bucks in para + high B2B temp
Standby gen @ Cresta Alarm
NE70 Ramp mg
Both Pae units Reserve S/D

Internal

Rock Creek Operations, Rock Creek Switching Center
EAP TESTING Bucks area
Bucks U1U #4 open

SHIFT TURNOVER CHECKLIST

DATE: 7/14/21
SHIFT: DAY NIGHT

OPERATOR SIGNATURE: _____
OPERATOR SIGNATURE: _____



- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: 10 MW Bucks 1 CARD UNTIL 10:00 | Bucks 1101 DE-ENERGIZED
NF70 640 CFS

DATE: 7-15-21
SHIFT: DAY NIGHT

OPERATOR SIGNATURE _____
OPERATOR SIGNATURE _____



- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: Diesel Gen Cresta / Clearance
Bucks w/ BZB temp alarms
Residual load lowered
Joe UZ Para

Internal

SHIFT TURNOVER CHECKLIST

DATE: 7-15-21
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: _____
OPERATOR SIGNATURE: _____

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: Poe2 para, Books Alarm/trip points advised
Cresta Dam on Dieselgen.
May be Evacuated to Caribou

DATE: 7/16/21
SHIFT: DAY / NIGHT

OPERATOR SIGNATURE: _____
OPERATOR SIGNATURE: _____

- Events during shift
- Current Voltage Order
- GCC Voltage Confirmation Call Made
- AVR/PSS Abnormal/Normal
- IFR's
- Fire Index
- Weather (Storms, flow increases, etc.)
- SCADA Tags/ alarms
- Operator Log

- AFW's Processed
- FWN's
- Clearances need to be checked
- Road Conditions (rocks, accidents, etc.)
- Ongoing Work (Emergency, outages, crews, etc.)
- Tomorrow's scheduled work
- Roving Operator special work/locations
- Log shift change in ODMS
- Review shift taking JSA

NOTES: NORMAL VOLTAGE; SIP T; CRESTA DAM;

Internal

Rock Creek Operations, Rock Creek Switching Center