From:	
To: Sent: Subject:	7/14/2021 11:36:01 AM RE: Dixie Fire - Preliminary Summary (Update)

Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 9:55 AM

To:

Subject: FW: Dixie Fire - Preliminary Summary (Update)

Privileged and Confidential

Redacted for Privilege

F	r	0	n	n	

Sent: Wednesday, July 14, 2021 9:54 AM

To:

Cc:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 9:36 AM

To:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

Privileged and Confidential

Redacted for Privilege

Redacted for Privilege

Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 8:09 AM

To:

Cc:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 7:53 AM

To: Cc:

Subject: Fwd: Dixie Fire - Preliminary Summary (Update)

Redacted for Privilege

Get Outlook for iOS

From:

Sent: Wednesday, July 14, 2021 7:50 AM

Subject: Fwd: Dixie Fire - Preliminary Summary (Update)

Get Outlook for iOS

From: Sent: Wednesday, July 14, 2021 7:03:01 AM

To:

Subject: Dixie Fire - Preliminary Summary (Update)

This report is confidential and preliminary. It is for internal use only. It is based on available information as of the date of this communication, and the data is subject to change.

Preliminary Summary Information as of 0630 7/14: Dixie Fire in Oroville, Butte County, North Valley. Tier 3

Unfortunately CAL FIRE did not get good containment on the 2 acre fire, which was surrounded by retardant and practically stopped yesterday evening. About 2230 last night the fire spread outside of the "containment" lines and ran upslope.

HAWK entry at 0621 7/14: Per PSS, Dixie Fire is now estimated at 100+ acres burning both moderately upslope and downcanyon towards Canyon Creek Road and our T-line assets. Electric T and D teams are engaged. SIPT looking at pre-treatment opportunities near the heel of the fire on the Bucks Creek 1101 Circuit.

HAWK entry at 1848 7/13: Per Twitter information, 1-to-2-acre vegetation fire surrounded by retardant drops and a road. Fire is burning in steep terrain with heavy timber.

Per ILIS Report: Tman found FUCO blown at 1640. Tman reported tree into line with a grass fire. DO notified **internal** EIR hotline at approximately 2250.

Assets in area: Rock Creek-Poe 230 KV line, Bucks Creek-Rock Creek-Cresta 230 KV, Caribous-Palermo 115 KV, Bucks Creek 1101 in the area along with the Cresta Dam.

Ell has been notified and gathering intel.


First IRWIN Time	1715 7/13	First SM Last Gasp Time	 None. "No AMI" noted for 3 customers.
			Per ILIS, Outage Times: • 2 customers at 16:40 • 1 additional customer at 20:30
First GOES Satellite Time	2226 7/13	First SM Partial Voltage Time	None
OIS Outage #	1403761	Distribution SCADA Relay and Alarm Times	None
Max and current customer impacts	3	Transmission SCADA Relay and Alarm Times	None
Acre Size and Containment	100+ acres 0% Containment	Tier	3

• View as of 0300 7/14



Maps

- Purple Line: Rock Creek Poe 230 KV
- Purple Line: Bucks Creek-Rock Creek-Cresta 230 KV
- Purple Line: Caribou-Palermo 115 KV
- Green Line: Caribou-Table Mtn 230 KV



- Red line: Bucks Creek 1101
- Pink dots are modis hot spots

Pluman			K		
Plan	Same cirth			2	an Racine Lost
				N.	Ra
10.5		mic Byur of			

Customer SmartMeter Network Status

							Affecte	d Cust	om	er List						
3 Custom	ners for S	SWITCH	{941}	(max	100) rec.	are returned)		Save Mis	-Assigned	Default Sort	All Current	All Affected	Print	Close
utage No. 14	03761												Wedne	esday, July 1	4, 2021 0	6:34
Mis- ssigned?	SPID	Name	Priority	Rate Schd.			Xfmr.ID	AMI Info Restoration)	AMI Info (Part Volt)	Meter#	Service Address	Premise Pho	one Cont	act Phone	City	Zip
042	22823430			LS3	OTH	17733	221758680519			1010245675						
075	92610405		k.	A1	COM	17733	221758680519	No AMI		1010241166						
079	92690705			A1	COM	941	221768080980	No AMI	1	1010241169						

ILIS

-					
P	a	ra	d	15	e
			-		~

	2	1-0089207					
Outages							
Circuit	102211101, BUCKS CREEK-1101	District	Paradise				
Туре	Unplanned	Customer Minutes	Sus 460 Mom 0 Adj Sus 460 CAIDI 15				
Customers		Weather	Clear, 32-90F				
Active	YES	Fault Type	Line to Line				
Interval	Sustained	Action Required	No				
EquipID	17733	Construction Type	OH				
Equipment Type	Fuse	OIS Outage#	1403761				
Equipment Condition	Conductor, Overhead, Normal	Targets					
Crew Notified Time		Supervisor Notified					
Equipment Address	CRESTA DAM TAP W/O SW 17183	Fire Mitigation	No				
Fault Location	1ST SPAN LD SIDE OF FUCO 17733	and a second second second second					
Previous Switching							
Details	VEG FIRE IN AREA						
Action Description							
Cause	Vegetation, Tree - fell into line	No Access Reason					
Distribution Wire Down	No	Wire Down Energized	No				
Multi Damage Location	No	# of Operations					
Counter Read		Created By					
Outage Level	Distribution Circuit	Last Updated By					
Responsible Organization	Distribution	Fault Location Info					
GPS MA Data		Latitude & Longitude					
FNL	07/13/21 16:40	Reviewed By	Not Required				
End Date		Reviewed By Date	And a Country of Country of				
Actions							
Date Description		Customers Restored Out Out	t Customer Minutes				
	FOUND FUCO 17733 #1 AND #2 BLOWN OPENED AGGED MOL -TREE IN THE LINE - GRASS FIRE- CALLED ED OF FUSES BLOWN AT 2250						
07/13/21 20:30 SWITCH 941 OPEN SWITCH FOR FIRE		-1 3 230	460				

This report is confidential and preliminary. It is for internal use only. It is based on available information as of the date of this communication, and the data is subject to change.

Director, Wildfire Safety Operations

Some of the measures included in this email are contemplated as additional precautionary measures intended to further reduce the risk of wildfires.