From:

To:

**Sent:** 7/14/2021 9:55:16 AM

**Subject:** FW: Dixie Fire - Preliminary Summary (Update)

Privileged and Confidential

# Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 9:54 AM

To:

Cc:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

### **Redacted for Privilege**

From:

Sent: Wednesday, July 14, 2021 9:36 AM

To:

Cc:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

Privileged and Confidential

### Redacted for Privilege

# Redacted for Privilege



### Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 8:09 AM

To:

Cc:

Subject: RE: Dixie Fire - Preliminary Summary (Update)

## Redacted for Privilege

From:

Sent: Wednesday, July 14, 2021 7:53 AM

To:

Subject: Fwd: Dixie Fire - Preliminary Summary (Update)

## Redacted for Privilege

Get Outlook for iOS

From:

Sent: Wednesday, July 14, 2021 7:50 AM

To:

Subject: Fwd: Dixie Fire - Preliminary Summary (Update)

Get Outlook for iOS

From:

Sent: Wednesday, July 14, 2021 7:03:01 AM

To:

Subject: Dixie Fire - Preliminary Summary (Update)

This report is confidential and preliminary. It is for internal use only. It is based on available information as of the date of this communication, and the data is subject to change.

Preliminary Summary Information as of 0630 7/14: Dixie Fire in Oroville, Butte County, North Valley. Tier 3

Unfortunately CAL FIRE did not get good containment on the 2 acre fire, which was surrounded by retardant and practically stopped yesterday evening. About 2230 last night the fire spread outside of the "containment" lines and ran upslope.

**HAWK entry at 0621 7/14:** Per PSS, Dixie Fire is now estimated at 100+ acres burning both moderately upslope and downcanyon towards Canyon Creek Road and our T-line assets. Electric T and D teams are engaged. SIPT looking at pre-treatment opportunities near the heel of the fire on the Bucks Creek 1101 Circuit.

**HAWK entry at 1848 7/13:** Per Twitter information, 1-to-2-acre vegetation fire surrounded by retardant drops and a road. Fire is burning in steep terrain with heavy timber.

**Per ILIS Report:** Tman found FUCO blown at 1640. Tman reported tree into line with a grass fire. DO notified **internal** EIR hotline at approximately 2250.

Assets in area: Rock Creek-Poe 230 KV line, Bucks Creek-Rock Creek-Cresta 230 KV, Caribous-Palermo 115 KV, Bucks Creek 1101 in the area along with the Cresta Dam.

Ell has been notified and gathering intel.

| First IRWIN Time                 | 1715 7/13                    | First SM Last Gasp Time                  | None. "No AMI" noted for 3 customers.   |
|----------------------------------|------------------------------|--|---|
|                                  |                              |  | Per ILIS, Outage Times:  2 customers at 16:40  1 additional customer at 20:30 |
| First GOES Satellite Time        | 2226 7/13                    | First SM Partial Voltage Time            | None  |
| OIS Outage #                     | 1403761                      | Distribution SCADA Relay and Alarm Times | None  |
| Max and current customer impacts | 3                            | Transmission SCADA Relay and Alarm Times | None  |
| Acre Size and Containment        | 100+ acres<br>0% Containment | Tier                                     | 3   |

View as of 0300 7/14



### Maps

• Purple Line: Rock Creek Poe 230 KV

• Purple Line: Bucks Creek-Rock Creek-Cresta 230 KV


Purple Line: Caribou-Palermo 115 KV
Green Line: Caribou-Table Mtn 230 KV



Red line: Bucks Creek 1101Pink dots are modis hot spots



### **Customer SmartMeter Network Status**



**ILIS** 

#### Paradise

| 21-0089207  |  |                           |  |  |  |
|---|--|---------------------------|--|--|--|
| Outages   |  |                           |  |  |  |
| Circuit   | 102211101, BUCKS CREEK-1101  | District                  | Paradise                               |  |  |
| Туре  | Unplanned  | <b>Customer Minutes</b>   | Sus 460 Mom 0 Adj Sus 460 CAIDI 153    |  |  |
| Customers   |  | Weather                   | Clear,32-90F                           |  |  |
| Active  | YES  | Fault Type                | Line to Line                           |  |  |
| Interval  | Sustained  | Action Required           | No                                     |  |  |
| EquipID   | 17733  | Construction Type         | OH                                     |  |  |
| Equipment Type                                    | Fuse   | OIS Outage#               | 1403761                                |  |  |
| Equipment Condition                               | Conductor, Overhead, Normal  | Targets                   |  |  |  |
| Crew Notified Time                                |  | Supervisor Notified       |  |  |  |
| Equipment Address                                 | CRESTA DAM TAP W/O SW 17183  | Fire Mitigation           | No                                     |  |  |
| Fault Location                                    | 1ST SPAN LD SIDE OF FUCO 17733   |                           |  |  |  |
| Previous Switching                                |  |                           |  |  |  |
| Details   | VEG FIRE IN AREA   |                           |  |  |  |
| Action Description                                |  |                           |  |  |  |
| Cause   | Vegetation, Tree - fell into line  | No Access Reason          |  |  |  |
| Distribution Wire Down                            | No   | Wire Down Energized       | No                                     |  |  |
| Multi Damage Location                             | No   | # of Operations           |  |  |  |
| Counter Read                                      |  | Created By                |  |  |  |
| Outage Level                                      | Distribution Circuit   | Last Updated By           |  |  |  |
| Responsible Organization                          | Distribution   | Fault Location Info       | -                                      |  |  |
| GPS MA Data                                       |  | Latitude & Longitude      |  |  |  |
| FNL   | 07/13/21 16:40   | Reviewed By               | Not Required                           |  |  |
| End Date  |  | Reviewed By Date          |  |  |  |
| Actions   |  |                           |  |  |  |
| Date Description                                  |  | Customers Restored Out Ou | nutes Customer<br>t Minutes            |  |  |
|   | FOUND FUCO 17733 #1 AND #2 BLOWN OPENED<br>GGED MOL-TREE IN THE LINE - GRASS FIRE- CALLED<br>ED OF FUSES BLOWN AT 2250 | 0 2                       | 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |  |  |
| 07/13/21 20:30 SWITCH 941 OPEN<br>SWITCH FOR FIRE |  | -1 3 230                  | 460                                    |  |  |

This report is confidential and preliminary. It is for internal use only. It is based on available information as of the date of this communication, and the data is subject to change.

Director, Wildfire Safety Operations

Some of the measures included in this email are contemplated as additional precautionary measures intended to further reduce the risk of wildfires.