


From:



To:
CC:

Sent: 7/14/2021 4:05:59 PM

Subject: 120135341 Work Verification More Information Needed - North Valley Table Mountain

To Whom It May Concern:

Thank you for submitting Notification #120135341 for review and verification. The following items must be addressed before the notification may be processed by the Work Verification Team:

Work Verification Comments:

Unable to verify structure ID from photos; Please confirm or resubmit photos of Structure ID

Notification # 120135341

Order: 44860154


Headquarters/ Main Work Center: Table Mountain

Line Name: CRESTA-RIO OSO

Structure ID # 020/165

Latitude:

Longitude:

Please log into the construct app and append the submission under this notification and email  once this information has been resubmitted. **DO NOT RESUBMIT THROUGH PRONTO.** Please resubmit on the app within 2 days of this email to remain in compliance with the requirements of the Construction Work Verification Program.

Thank you,



T-Line Work Verification Team