



Code Description Job Code Field Activity Code Completion Code Hazard Code

Parameter(s):

Field Order ID: 0009119619 Taken By: [REDACTED] Time Taken: 09:36 Rescheduled By:
 Premise ID: 0000005597 Date Taken: 7/13/21 Status: Completed

Customer Information

Account ID:
 Hm Ph:
 Bus Ph:
 Cont Ph:
 Name:
 Address: UNKNOWN
 PREMISES DO NOT
 CHANGE
 City: STORRIE

Premise Information

Prem Type: UNKNOWN
 Prem Est Dt:
 Bus Activity:
 Home Area: VFPH101
 Sub Area: VFPS101
 Check Digit:
 Tot Amt Owing:
 Cash Only Flag:
 SL:
 LS:
 Gas Sp Id:
 Elec Sp Id: 0000005599
 MtrRd Route: BFM01
 Prior Leak Date:

New Business/ Disconnect-Reconnect

Contractor:
 Contractor Ph:
 Contractor Waiting:
 Job Owner:
 Job Owner Ph:
 Site Ready:

Completion Information

Job Code 1: 1240 - E Unspecified-Outside
 Job Code 2: -

Fld Act Type 1: ELEUNSP0
 Fld Act Type 2:
 Fld Act Type 3:
 Fld Act Type 4:
 FAS Priority: 1
 MIR:
 OEC:

Comp Code 1: 1190 - E Tree or Obj On Wire
 Comp Code 2: -
 Comp Code 3: -
 Comp Code 4: -
 Comp Code 5: -
 Comp Code 6: -
 Comp Code 7: -
 Comp Code 8: -
 Comp Code 9: -
 Comp Code 10: -

Elec Completion Reason: -
 Gas Completion Reason: -

Surveys / Misc.

Electric:

Survey 1:
 Survey 2:
 Survey 3:
 Call Ahead Attempt:
 Call Ahead Success: Y
 Return To Record:
 Service Rpt: Y

Gas:

Survey 1:
 Survey 2:
 Survey 3:
 Call Ahead Attempt:
 Call Ahead Success:
 Return To Record:
 Service Rpt:

Service History

Service Hist 1:
 Service Hist 2:

PM Information

PM Order:

PM Operation:

Order Dates/Misc.

App Start Date/Time: 7/13/21 08:00
 App End Date/Time: 7/13/21 20:00
 Dispatcher ID: [REDACTED]

Technician Information:

Tech ID: [REDACTED]
 Sensit#
 Comp Date/Time: 7/13/21 23:02
 Dispatched Date/Time: 7/13/21 10:47
 Acknwldg Date/Time:
 En Route Date/Time: 7/13/21 11:43
 On Site Date/Time: 7/13/21 12:29

Cancel Information:

User ID:
 Rsn Code:
 Code Desc:

Attachments

of Attachments:
Deviation
 Approved Deviation:
 Supervisor ID:





Code Description Job Code Field Activity Code Completion Code Hazard Code

Parameter(s):

Field Order ID:	0009119619	Taken By:	██████████	Time Taken:	09:36	Rescheduled By:	
Premise ID:	0000005597	Date Taken:	7/13/21	Status:	Completed		

Existing Hazards:

Hazard Code 1:	-	Hazard Date 1:	
Hazard Code 2:	-	Hazard Date 2:	
Hazard Code 3:	-	Hazard Date 3:	
Hazard Code 4:	-	Hazard Date 4:	
Hazard Code 5:	-	Hazard Date 5:	
Hazard Code 6:	-	Hazard Date 6:	
Hazard Code 7:	-	Hazard Date 7:	
Hazard Code 8:	-	Hazard Date 8:	
Hazard Code 9:	-	Hazard Date 9:	
Hazard Code 10:	-	Hazard Date 10:	
Hazard Code 11:	-	Hazard Date 11:	
Hazard Code 12:	-	Hazard Date 12:	
Hazard Code 13:	-	Hazard Date 13:	
Hazard Code 14:	-	Hazard Date 14:	
Hazard Code 15:	-	Hazard Date 15:	
Hazard Code 16:	-	Hazard Date 16:	
Hazard Code 17:	-	Hazard Date 17:	
Hazard Code 18:	-	Hazard Date 18:	
Hazard Code 19:	-	Hazard Date 19:	
Hazard Code 20:	-	Hazard Date 20:	

New Hazards

New Hazard Code 1:	-	New Hazard Code 11:	-
New Hazard Code 2:	-	New Hazard Code 12:	-
New Hazard Code 3:	-	New Hazard Code 13:	-
New Hazard Code 4:	-	New Hazard Code 14:	-
New Hazard Code 5:	-	New Hazard Code 15:	-
New Hazard Code 6:	-	New Hazard Code 16:	-
New Hazard Code 7:	-	New Hazard Code 17:	-
New Hazard Code 8:	-	New Hazard Code 18:	-
New Hazard Code 9:	-	New Hazard Code 19:	-
New Hazard Code 10:	-	New Hazard Code 20:	-



Parameter(s):

Field Order ID: 0009119619

Taken By: [REDACTED]

Time Taken: 09:36

Premise ID: 0000005597

Date Taken: 7/13/21

Status: Completed

CSR Remarks:

CHECK FUSE 805 - BUCKS CREEK 1101 - PER D O [REDACTED]

EMR Ord Detail:

EMR Completion:

Dispatcher:

PARADISE TAG PER TMAN [REDACTED]

Electric Remarks:

Found tree on line with 2 fuses blown and 1 still energized. open remaining. Called for 911

Gas Remarks:

Extended:

Cancel Notes:



Parameter(s):

Field Order ID: 0009119619

Taken By: [REDACTED]

Time Taken: 09:36

Premise ID: 0000005597

Date Taken: 7/13/21

Status: Completed

Self-Check Tools:

2-Minute Rule Y

Smith Driving Keys Y

3-Way Communication Y

Self-Check Remarks:

Self-Check Local Hazards:

Traffic

Person Hazards:

Premise Hazards:



Parameter(s):

Field Order ID: 0009119619

Taken By: [REDACTED]

Time Taken: 09:36

Premise ID: 0000005597

Date Taken: 7/13/21

Status: Completed

Energy Savings Assistance(ESA):

Finance Capped

Furnace Repair

Water Htr Capped

Water Htr Repair



Traffic