
From: [REDACTED]
Sent: 7/14/2021 1:39:24 PM
To: [REDACTED]
CC: [REDACTED]

Subject: Bucks/Grizzly - IBEW Safety Audit
Attachments: Desabla IBEW Safety Audit Form with roads.doc
Location: Bucklin Road/Hwy 162 Intersection

Start: 9/15/2021 8:30:00 AM
End: 9/15/2021 5:30:00 PM
Show Time As: Busy

Required Attendees: PG O&M Rock Crk Ops; [REDACTED]
Optional Attendees: [REDACTED]

Rescheduled due to impacts from Dixie Fire.

All –

This is a placeholder for the Bucks Lake/Grizzly PH IBEW GRST Safety Audit (Bucks Dam, Lower Bucks Dam, Grizzly Reservoir and Grizzly PH). We need at least one Water System Repair Person or Operator who knows the area to lead the team, and representatives from the GRST and IBEW to participate in the effort.

Please let me know if you will be able to participate.

Thanks,

[REDACTED]
PM-DeSabra Hydro
[REDACTED]